(Page 2 of 2)

Council Priority Funds - Application

PRIORITY FUND INFORMATION - Completed by Applicant Organization Name Josephburg Community Church Cemetry Address 21380 TWP Rd 550 Civic address is 21338 TWP.Rd 550 Street and number Subdivision if rural Province Alberta Contact person Stan Thomas Telephone 7806162458 Email address (optional) Ruth.stanthomas@gmail.com Project Type ☐ Event X Project Expense Amount Requested \$ 5500.00 Brief description of request The project is to rework the eastern driveway entrance into the cemetery. Over the last many years the slope of the driveway has increased due to roadwork which makes the entrance rather dangerous to drive in. We have obtained one quote to remove existing earth and backfill with clay and 4-6 inches of crushed gravel. In order to obtain a proper slope we need to extend the driveway in width and length Stan Thomas Print name Please remember to attach a proposed budget and request letter to this request.

Collection and use of personal information

Number of attached pages 3

Personal information is collected under the authority of section 33(c) of the *Freedom of Information and Protection of Privacy Act* and will be used to manage and administer Council Priority Funds. Please be aware that information provided may be made public. If you have questions regarding the collection, use or disclosure of this information, contact Vicky Cushman at 780-464-8098.

Josephburg Community Church

21380 TWP RD 550
Fort Saskatchewan, AB
T8L 4B9
Ph: 780-998-9331
josepburgcommunitychurch@albertacom.com

October 18, 2022

Office of the Elected Officials Strathcona County 2001 Sherwood Drive Sherwood Park, Alberta T8A 3W7

On behalf of Josephburg Community Church, we are requesting that the Office of Elected Officials look at our need for reworking the entrance into the Josephburg Community Church Cemetery. The cemetery was established in 1893. The current driveway entrance into the cemetery was built in roughly 1960 when the cemetery expanded and at this time Township Road 550 was gravel. Over the years Township Road 550 has improved and widened which has caused the slope from Township Road 550 into the cemetery to become very steep and dangerous for anyone entering and exiting the cemetery. Around 2018 the railroad was also lifted causing Township Road 550 to be lifted as well from the entrance. Throughout the past 15 to 18 years, consistory members of Josephburg Community Church have requested assistance through word of mouth to the councillors of area 5. Recently Aaron Nelson suggested that we apply for assistance through Council Priority Funds. If the Elected Officials have any questions at all or require further information, please have them contact me. Thank you for taking the time to consider Josephurg Community Church Cemetery for funding.

Kind Regards,

Stan Thomas
Josephburg Community Church
ruth.stanthomas@gmail.com
780.616.2458

Cemetery gate Renovation project				
	Estimate	Lowest Quote	GST	Total
Expand d riveway to 18 fet wide and 50 feet long	7500	5400		
Provide for solar operated gate	8000	6250		
50 feet	8500	6000		
Install new gate and posts as required	8500	5000		
		22650		
Ground work		4685	234.24	4919.24
Add 2 feet to ground work		4950	247.5	5197.5
Metal work , need to decide on options		17250	862.5	18112.5